

Site Name	Latitude, Longitude	Address	Site Type	Past Response Actions	Anticipated Upcoming Response Actions	Are Response Actions Complete?	Is Site Suitable for Unrestricted Use?	Are Institutional Controls in Place?	Lead Agency	Yakama Nation Status
<b>LOWER COLUMBIA RIVER</b>										
<b>Washington Side</b>										
Pacific Wood Treating	45.818, -122.748	111 West Division Ridgefield, WA 98642	Wood Treating Facility	Upland and In- Water Remedial Actions	Order/Decree/Amendment/Cleanup Action Plan/Performance Monitoring	No	TBD	Unknown	WA Dept. of Ecology	Tracking Project
Former Reynolds Aluminum Plant	46.141, -122.996	4029 Industrial Way Longview, WA 98632	Former Aluminum Smelting Facility	Early Actions	Order/Decree/Amendment/Cleanup Action Plan and Implementation	No	TBD	Unknown	WA Dept. of Ecology	Tracking Project
ALCOA Vancouver	45.651, -122.731	5701 NW Lower River Rd. Vancouver, WA 98666	Former Aluminum Smelting Company	Remedial Actions/ Supplemental Cleanup Plan/ Consent Decree	Active Operation and Maintenance/Monitoring	Yes	TBD	Yes	WA Dept. of Ecology	Tracking Project
Weyerhaeuser Longview	46.129, -122.989	3401 Industrial Way Longview, WA 98632	Pulp and Paper Complex	NPDES Permit Update	N/A	N/A	TBD	N/A	WA Dept. of Ecology	Tracking Project
Clean Earth Burlington	45.572, -122.337	625 S 32ND ST, Washougal, WA 98671	Paper Industry Dangerous Waste Management Facility	Agreed Order/ Permit for Corrective Action/Remedial Investigation and Feasibility Study /Public Participation Plan	Cleanup Started/Monitor Groundwater/Developing Cleanup Action Plan	No	No	No	WA Dept. of Ecology	Tracking Project
Georgia Pacific Consumer Products	45.58484, -122.40565	401 NE Adams St. Camas, WA 98607	Pulp and Paper Complex	Agreed Order for Remedial Action	Awaiting Cleanup	No	No	Unknown	WA Dept. of Ecology	Tracking Project
<b>Oregon Side</b>										
Cascade Locks Lumber Co.	45.683, -121.860	Industrial Park Way Cascade Locks, OR 97014	Former Lumber Mill	Remedial Actions	ODEQ No Further Action	No	TBD	Unknown	ODEQ	Tracking Project
Zidell Waterfront Property	45.500, -122.670	3121 SW Moody Ave. Portland, OR 97201	Former WWII Ship Scrap Metal Recycling Facility	Remedial Actions	Continue Operation and Maintenance	No	TBD	Engineered cap, Easement Equitable Servitude	ODEQ	TBD

Armstrong World Industries	45.839, -122.818	1645 Railroad Ave., St. Helens, OR 97051	Fiberboard Production Plant	Draft Remedial Investigation/Feasibility Study	In-water Investigation and Upland Remediation	Unknown	TBD	Engineered Cap, Easement and Equitable Servitudes	ODEQ	Tracking Project
Port of St. Helens Multnomah Plywood	45.834, -122.825	58144 Old Portland Rd., St. Helens, 97051	Plywood Manufacturing Mill	Remedial Investigation/	Unknown	Unknown	TBD	Unknown	ODEQ	Tracking Project
Port of St Helens Creosote Pope & Talbot	45.841, -122.809	1550 Railroad Ave., St. Helens, OR, 97052	Wood Treating Facility	Remedial Investigation/Supplemental Remedial Investigation/Proposed Plan	ODEQ Partial No Further Action	Unknown	TBD	Use Restriction for Groundwater and Land, Easement and Equitable Servitudes	ODEQ	Tracking Project
Boise White Paper	45.848, -122.803	1300 Kaster Rd., St. Helens, OR, 97051	Pulp and Paper Mill	Remedial Investigation/Feasibility Study/Supplemental Feasibility Study/Proposed Plan	Record of Decision	Unknown	TBD	Unknown	ODEQ	Tracking Project
Boise Cascade Veneer	45.860, -122.796	South First St., St. Helens, OR, 97051	Veneer Mill	Expanded Preliminary Assessment/Prospective Purchaser Agreement	ODEQ No Further Action	Unknown	TBD	Use Restriction for Groundwater and Land, Engineered Cap and Easement and Equitable Servitudes	ODEQ	Tracking Project

**MIDDLE COLUMBIA RIVER SITES**

**Washington Side**

Boise Cascade/Yakima City Landfill	46.611, -120.492	805 North 7th Street, Yakima, WA 98901	Former Lumber Mill and City Landfill	Voluntary Cleanup Remedial Investigation	Remedial Investigation Work Plan/Feasibility Study/Interim Action Plan	No	TBD	None	WA Dept. of Ecology/City of Yakima	Tracking Project
------------------------------------	------------------	--	--------------------------------------	--	--	----	-----	------	------------------------------------	------------------

Coleman Oil	47.417, -120.302	3 Chehalis St. Wenatchee, WA 98841	Bulk Fuel Facility	Draft Remedial Investigation/Feasibility Study	Feasibility Study/Interim Action Plan/Groundwater Monitoring	Unknown	TBD	None	WA Dept. of Ecology	Tracking Project
Yakima Training Center	46.675, -120.365	Near Selah, WA 98901	Military Training Facility/Dangerous Waste Management Facility	Remedial Actions/Remedial Investigation Workplan/Groundwater Monitoring	Institutional Controls Implemented/Groundwater monitoring	No	TBD	Unknown, Selected Remedy 2/01/2021	WA Dept. of Ecology	Tracking Project
RAMCO Aluminum Waste Disposal	45.628, -121.125	104 PARALLEL ST Dallesport, WA 98617	Former Smelting Facility	Remedial Actions	WA Dept. of Ecology No Further Action	No	TBD	Unknown	WA Dept. of Ecology	Tracking Project
Columbia Gorge Aluminum Company	45.727, -120.682	85 John Day Dam Rd. Goldendale, WA 98620	Former Aluminum Smelting Company	Demolition of Former Aluminum Facility, Draft Remedial Investigation Work Plan	Remedial Investigation/Feasibility Study/Cleanup Action Plan	No	TBD	Environmen tal Covenant/R estrict Land Use/Ground water/Soil	WA Dept. of Ecology	Tracking Project
New City Cleaners	46.275, -119.284	747 Stevens Drive, Richland, WA 99352	Dry Cleaners	Remedial Investigation/Feasibility Study?Interim Action Construction/Performance Monitoring	Interim Action/Performance Monitoring	No	TBD	None	WA Dept. of Ecology	Tracking Project
Goodnoe Hills Treaty Fishing Access Site	45.706, -120.501	Near Goldendale, WA 98620	1970s Train Derailment	Remedial Actions- Confirmation Sampling	Ecology Groundwater Investigation	TBD	TBD	Unknown	U.S. Army Corps of Engineers	Tracking Project
<b>Oregon Side</b>										
Mosier Oil Spil	45.685, -121.404	Near Rock Creek Road Mosier, OR 97040	Train Derailment Oil Spill	Biosystem Treatment System and Groundwater Monitoring Wells	Decommission Biosystem Treatment System and Groundwater Monitoring Wells/Confirmation Sampling	Yes	TBD	Unknown	ODEQ	No Further Action**
Chem Waste - Arlington	45.6227, -120.2208	18177 Cedar Springs LN, Arlington OR 97812	Hazardous Waste Landfill	Groundwater Monitoring	Upland Site Characterization/Groundwat er Monitoring	Unknown	TBD	Unknown	ODEQ	Engaging in Permit Modification Process