

**PROJECT CONDITIONS**



EXISTING CONDITIONS



Looking downstream towards CED site #1



Looking downstream towards CED site #2



Looking downstream towards CED #3




Looking upstream from CED site #3

CED SITES photo credit: WSDOT and Chelan County



CED site #1: 1995 flood that washed out the SR 207 road prism near RM 4.5. Photo taken from the north looking south.



CED site #1: 1995 flood that washed out the SR 207 road prism near RM 4.5. Photo taken from the south looking north.



CED site #1: 2010 site conditions in Nason Creek where there have been 3 road maintenance repairs in the last 10 years.



CED site #2: April 2010 site conditions in Nason Creek under the powerline crossing.

PROJECT PHOTOS



